Hazard Alert



Hazard Summary:

As winter retreats and temperatures rise, there are more individuals working on roofs to remove snow. For some, this means working without the necessary fall protection.

This poses a significant risk to individuals because serious or fatal injuries can occur from falling.

Hazard Location:

Working at heights greater than three metres.



The Northwest Territories Occupational Health and Safety Regulations, Section 108. (1), states:

Before using a lifeline or lanyard, a worker shall ensure that the lifeline or lanyard is:

- free of imperfections, knots and splices, other than end (a) terminations:
- protected by padding where the lifeline or lanyard passes (b) over sharp edges; and
- protected from heat, flame or abrasive or corrosive materials (c) during use.

The Nunavut General Safety Regulations, Section 57, states:



Safe Work Practices:

Workers must use fall protection to prevent them from falling off a roof. This could include one, or a combination of, the following systems:

- Fall restraint system;
- Fall arrest system;
- Guarding with barriers and guard railing;
- Work platforms; or
- Safety nets.

We commit to safety. For more information on workplace health and safety, call us toll-free or visit our website.







